From: Christopher Ruhl
To: Gary Moore

Subject: Falcon Refinery Butane Tank
Date: 02/17/2010 07:01 AM
Attachments: butane tank.ppt

Gary-

I have highlighted the butane tank on the attached two slides. The tank is a large horizontal tank that has approximately 80psi according to the pressure gauge on the tank. Based on air monitoring it appears to be leaking from the bottom of the tank where there is a bolted flange. The flange and bolts are heavily corroded.



The Chris Ruhl USEPA Region 6 Federal On-Scene Coordinator (214) 665-7356 office